



PS059-90 Frame Assembly



Frame part list and code for schematics;

- Right frame corner - RFC Qty. 2
- Left frame corner - LFC Qty. 2
- 0" quick connect - 0QC Qty. 4
- 6" quick connect - 6QC Qty. 6
- 33" straight frame - 33ST Qty. 6

PS059-90 Panel Assembly



Frame part list and code for schematics;

- Stance Panel - FP040 Qty. 1
- FW Hitting Panel - FP016 Qty. 2
- R Endcap - RP165 Qty. 2